

# **ABS Diagnostics in Display Menu**



- ► Access the ABS M5 ECU directly from the display menu without the need for a laptop
- ▶ Display and clear ABS error memory
- ► Run bleed wizard
- ▶ Wheel speed and sensor checks

Bosch DDU devices are capable of accessing ABS diagnostics through the User Interaction Menu (UIM). The functionality provides similar diagnostics to the RaceABS software, but without the need for a computer and MSA-BOX II communication device. With the ABSDIAG unlock, ABS diagnostics are accessible in a pre-defined menu via RaceCon UIM configuration. The UIM requires buttons to be defined for general menu navigation; these buttons are typically integrated into the steering wheel or keypad. While the ABS diagnostics available in the UIM does not fully replace the RaceABS software, it does allow commonly used diagnostic features like error memory reading and clearing, sensor checks, and the repair bleed wizard to be done without a computer or MSA-Box II. With the ABSDIAG unlock, the user interaction with ABS M5 is much more convenient.

# **Application**

## Communication

Display CAN configurable by user for communication with ABS M5 ABS CAN1 for UIM diagnostic required (ABS and yaw rate sensor CAN)


#### **Software**

ABS Firmware	V0800 or later
Display Software	BASE_0615 or later
RaceCon	V2.12.0.9 or later

# **Ordering Information**

ABS Diagnostics in Display Menu ABSDIAG (Activation per device) Order number F02U.V03.003-01


## Dimensions




Error memory read/delete

	ERROR MEMORY
ABS connection	ok
Error count	6
Error 1 Short circuit of	f the WSS_FR st >
Error 2 Short circuit of	f the WSS_RL st >
Error 3 Pressure Sensor	Master Cylind:>
Error 4 Short circuit o	f the WSS_RL st >
Error 5 Short circuit o	f the WSS_RR st >
Error 6 Short circuit o	f the WSS_FL st >

Read error memory - Overview




Read error memory - Overview continued




Error entry details

	ERROR ENTRY
Debug1	00-00-00-00
Op. hours	2292.00
Power on mins	34.00
Status	0
Speed [m/s]	0.00
UBVR [V]	150.00
UBECU [V]	150.00
Back	×


Error entry details - continued



Bleeding wizard



Bleeding wizard routine



Wheel check

### Represented by:

Europe: Bosch Engineering GmbH Motorsport Robert-Bosch-Allee 1 74232 Abstatt Germany Tel.: +49 7062 911 9101 Fax: +49 7062 911 79104 motorsport@bosch.com

www.bosch-motorsport.de

North America:
Bosch Engineering North America
Motorsport
38000 Hills Tech Drive
Farmington Hills, MI 48331-3417
United States of America
Tel.: +1 248 876 2977
Fax: +1 248 876 7373
motorsport@bosch.com
www.bosch-motorsport.com

Asia-Pacific:
Bosch Engineering Japan K.K.
Motorsport
18F Queen's Tower C, 2-3-5 Minato
Mirai Nishi-ku, Yokohama-shi
Kanagawa 220-6218
Japan
Tel.: +81 45 650 5610
Fax: +81 45 650 5611

www.bosch-motorsport.ip

Australia, New Zealand and South Africa: Robert Bosch Pty. Ltd Motorsport 1555 Centre Road Clayton, Victoria, 3168 Australia Tel.: +61 (3) 9541 3901 motor.sport@au.bosch.com