

CCA Security Alerts

SECURITY ALERT

Apache Log 4j Vulnerability, CVE-2021-44228, Log4Shell

Affected Products

- none

Not Affected Products

- Customer Code Area products in all versions are not affected by this vulnerability.
- 3rd party products we redistribute to our CCA customers:
 - VxWorks® products in all versions are not affected by this vulnerability.
 - The Wind River Workbench product is not affected.

SECURITY ALERT

CVE-2021-4104 – Relating to new weakness found in Log4j1.2

Affected Products

- none

Not Affected Products

- Customer Code Area products in all versions are not affected by this vulnerability.
The log4j.jar file is delivered with our product, but not used in our application.
As an additional measure you may safely delete these two files in all instances of our CCA environment.
<CCA_root>\target\toolbox\datamanager\CalibData\lib\log4j.jar
<AddOnTools_x_x_x>\DataManager\default\CalibData\lib\log4j.jar
- 3rd party products we redistribute to our CCA customers:
 - VxWorks® products in all versions are not affected by this vulnerability.
 - The Wind River Workbench product is not affected.

Legal Restrictions

The sale of this Software Tool in Mexico is prohibited.

Due to embargo restrictions, sale of this Software Tool in Russia, Belarus, Iran, Syria, and North Korea is prohibited.

Represented by:

Europe:
Bosch Engineering GmbH
Motorsport
Robert-Bosch-Allee 1
74232 Abstatt
Germany
Tel.: +49 7062 911 9101
Fax: +49 7062 911 79104
motorsport@bosch.com
www.bosch-motorsport.de

North America:
Bosch Engineering North America
Motorsport
38000 Hills Tech Drive
Farmington Hills, MI 48331-3417
United States of America
Tel.: +1 248 876 2977
Fax: +1 248 876 7373
motorsport@bosch.com
www.bosch-motorsport.com

Asia-Pacific:
Bosch Engineering Japan K.K.
Motorsport
18F Queen's Tower C, 2-3-5 Minato
Mirai Nishi-ku, Yokohama-shi
Kanagawa 220-6218
Japan
Tel.: +81 45 650 5610
Fax: +81 45 650 5611
www.bosch-motorsport.jp

Australia, New Zealand and South Africa:
Robert Bosch Pty. Ltd
Motorsport
1555 Centre Road
Clayton, Victoria, 3168
Australia
Tel.: +61 (3) 9541 3901
motor.sport@au.bosch.com